



ROTAX MAX FR125 REBUILD PRICES

2340 South, West Temple | Salt Lake City, Utah 84115 | phone 801-972-4631 | www.msquaredkarting.com

Msquared is proud to be an Authorized Rotax Max Service Center, an honor we've held since 2001. We've rebuilt hundreds of Rotax Max engines each one with the utmost attention to quality, precision and performance.

Piston ring only		
Part	Part #	Price
Piston ring	215547	\$50.85
Base gasket	65048x	\$5.23
Certification seal	297040	\$5.17
Total (parts only)		\$61.25
Labor (1 hour)		\$55.00
Total		\$116.25

Top-end rebuild		
Part	Part #	Price
Piston w/ring	29629x	\$149.12
Piston pin	216135	\$20.62
Piston clips (2)	945635	\$2.98
Upper cage bearing	932026	\$35.54
Base gasket	65048x	\$5.23
Head o-ring	250280	\$4.97
Certification seal	297040	\$5.17
Total (parts only)		\$223.63
Labor (1.5 hours)		\$82.50
Total		\$306.13
Recommended		
Intake gasket	250521	\$4.52
Reeds (2)	224430	\$35.46
Exhaust valve gasket	250231	\$4.52
Crank seal	930675	\$12.73

Complete rebuild		
Part	Part #	Price
Piston and ring	29629x	\$149.12
Piston Pin	216135	\$20.62
Piston Clips	945635	\$2.98
Upper cage bearing	932026	\$35.54
Base gasket	65048x	\$5.23
Head o-ring	250280	\$4.97
Intake gasket	250521	\$4.52
Reeds	224430	\$35.46
Exhaust valve gasket	250231	\$4.52
Left side main seal	230425	\$12.73
Right side main seal	930675	\$12.73
Water pump seals	1420	\$16.00
Center case gasket	650490	\$7.00
Side cover gasket	650470	\$7.00
Crank rebuild kit	298879	\$349.30
Main bearings	832533	\$61.36
Certification seal	297040	\$5.17
Total (parts only)		\$734.25
Labor (3.5 hours)		\$192.50
Crank rebuild		\$70.00
Total		\$996.75
Cylinder (if needed)	223997	\$599.30
Cylinder o-ring	250160	\$5.25

Prices current as of 2/13/2008. Rotax parts prices subject to change without notice. Prices do not include shipping and handling.